




Republic of the Philippines
DEPARTMENT OF LABOR AND EMPLOYMENT
EMPLOYEES' COMPENSATION COMMISSION
ECC Building, 355 Sen. Gil J. Puyat Avenue, Makati City



Management System
ISO 9001:2015
www.tuv.com
ID #105081530



PURCHASE REQUEST

Division	Administrative Division		PR No.	18-10-425	
Section/Unit			Date:	4-Oct-18	
Stock No.	Unit	Item Description	Quantity	Estimated Unit Cost	Estimated Total Cost
	Lot	To deliver units, supply materials, breakers labors, installation, commissioning, leak testing, including charging of refrigerant, copper pipe lines and rubber insulation, (with refrigerant R410) dismantling of old units			
	units	5TR Floor Mounted Package Type Aircon (Inverter)	6	200,000.00	1,200,000.00
	units	2 HP Window Type Air-condition (Inverter)	5	35,000.00	175,000.00
		TOTAL			P1,375,000.00
Purpose	to replace the defective and unserviceable airconditioning units located at the various offices and areas of ECC building				
Requested By:	Approved By:				
	<hr/> MARIBEL S.T. OLIVEROS Chief, Administrative Division		<hr/>  STELLA ZIPAGAN-BANAWIS Executive Director		